OREGON CORNER RESTORATION FORM

SECTION 10

TOWNSHIP 1 SOUTH

RANGE 24 EAST

COUNTY: MORROW

DATE:

7/07/2022

CORNER DESIGNATION: E-17

PREVIOUS RENEWALS / SURVEYS,

1865: ORIGINAL GLO SURVEY, U.S. DEPUTY SURVEYOR DAVID P. THOMPSON SET A POST FOR CORNER OF SECTIONS 2. 3, 10 & 11 IN MOUND OF EARTH WITH CHARRED STAKE. PITS AS PER INSTRUCTIONS.

1909: MORROW COUNTY SURVEY 1173A, D.V. REID DID NOT FIND POST. HE SET A ROCK 18x10x8 MARKED C.S. AT POST TO FENCES RUNNING WEST AND NORTH AS ACCEPTED CORNER POSITION.

1927: O.W.R.&N.Co MAP V-ORE-08-8 HAS A TIE TO SECTION CORNER FROM THE CENTERLINE OF THE TRACK.

1931: ODOT MAP 4B-2-4 HAS A TIE TO SECTION CORNER FROM THE CENTERLINE OF HEPPNER HWY.

1979: MORROW COUNTY SURVEY 2015-1744C, W.E. GILLESPIE SHOWS CORNER POSITION BUT DOES NOT STATE FINDING MONUMENT.

MONUMENT and ACCESSORIES FOUND: (CONDITION AND SOURCE)

2022: NO EVIDENCE OF CORNER FOUND.

(SEE MORROW COUNTY SURVEY 2022-1994C)

DIAGRAM:



MONUMENT and ACCESSORIES SET (PROCEDURES and DESCRIPTION)

SET 5/8"X30" REBAR W/ 2" ALUMINUM CAP, ±1.5' BELOW GROUND. STAMPED AS SHOWN ABOVE.

(SEE MORROW COUNTY SURVEY 2022-1994C)

REFERENCES SET:

SET 5/8"X24" REBAR WITH RED PLASTIC CAP STAMPED "RSI CONTROL" N7°56'49"E 20.11 FEET SET 5/8"X24" REBAR WITH RED PLASTIC CAP STAMPED "RSI CONTROL" N85°55'44"E 65.02 FEET SET 5/8"X24" REBAR WITH RED PLASTIC CAP STAMPED "RSI CONTROL" S25°51'32"E 129.08 FEET SET 5/8"X24" REBAR WITH RED PLASTIC CAP STAMPED "RSI CONTROL" S35°15'47"W 113.97 FEET RP-1 RP-2 RP-3 RP-4

LOCATION and COMMENTS

CORNER FALLS IN CATTLE PEN. ACCESSORIES SET ON OUTSIDE FACES OF FENCES.

SURVEYORS SEAL

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGO

MARCH 09, 2021 BRENTON A. GRIFFIN

93754PLS RENEWS: 06/30/2023

RECEIVED BY:

MORROW COUNTY SURVEYOR

DATE 8-11-2022

REC'D BY: MK

NO. 1524E17

FIRM / AGENCY

ROGERS SURVEYING, Inc., P.S. 1455 COLUMBIA PARK TRAIL, #201

RICHLAND, WA 99352

(509) 783-4141