OREGON CORNER RESTORATION FORM

SECTION 27

TOWNSHIP 1 SOUTH

RANGE 25 EAST

COUNTY: MORROW

DATE:

09/15/2015

CORNER DESIGNATION: T-17

PREVIOUS RENEWALS / SURVEYS, etc.


ORIGINAL CORNER SET BY U.S. DEPUTY SURVEYOR DAVID P. THOMPSON IN 1865.

DAVID KRUMBEIN, PLS 933, DENOTES SETTING A BRASS CAP AT THIS CORNER AS SHOWN COUNTY SURVEY D-623-K, DATED 6/15/83

MONUMENT and ACCESSORIES FOUND: (CONDITION AND SOURCE)

NO EVIDENCE WAS FOUND OF THE KRUMBEIN BRASS CAP. MONUMENT WAS APPARENTLY DESTROYED.

DIAGRAM:



MONUMENT and ACCESSORIES SET (PROCEDURES and DESCRIPTION)

CORNER WAS RE-ESTABLISHED FROM RECORD POSITION PER SURVEY D-623-K, MORROW COUNTY SURVEY RECORDS. SET 2-1/2" DIAM. BRASS CAP ON 1"X30" GALVANIZED IRON PIPE STAMPED AS SHOWN ABOVE. MONUMENT FALLS 1.8' SOUTH OF CORNER OF FENCES BEARING SOUTH AND WEST.

REFERENCES SET:

RP-1 SET 5/8"x30" REBAR NORTH 101.49 FEET RP-2 SET 5/8"x30" REBAR EAST 25.89 FEET RP-3 SET 5/8" REBAR SOUTH 32.68 FEET RP-4 SET 5/8" REBAR WEST 35.03 FEET

LOCATION and COMMENTS

CORNER IS LOCATED APPROXIMATELY 830' FEET EAST OF STATE HIGHWAY 207 NEAR THE SOUTHEAST CORNER OF THE LEXINGTON AIRPORT

SURVEYORS SEAL

RECEIVED BY:

MORROW COUNTY SURVEYOR

DATE 9-16-2015

REC'D BY: **5.K.H.**

NO. 1525T17

Survey C-1348-M

FIRM / AGENCY

ROGERS SURVEYING, Inc., P.S. 1455 COLUMBIA PARK TRAIL, #201 RICHLAND, WA 99352

(509) 783-4141

REGISTERED PROFESSIONAL AND SURVEYOR aug B. Wagner ØREGON JUNE 30, 1997 GARY B. WAGNER