History of original corner establishment

originally established 1882 dated 1881. under Contract Survey

approved Feb. established 21, by De 1941. Dependent Resurvey authorized 1938

16 1/4 21 1938	DIAGRAM T5S R28E

Description of corner evidence found:

inch iron pipe, with 2 1/2 inch brass which cap marked as shown above

Tree30" spruce alive and standing, blaze healed, (record 17" White Fir) bears N 29° scar visible. W (record), 102.3' (record).

30" Tamarack, dead and standing, bears scribing 1/4 S21 BT legible. Ŋ 9 Ŋ (record), 90.4' (record)

Original pipe monument was at location as determined portion of small earthen d dam. s found lying horizontal by both Bearing Trees. lam. Built mound of sto stone This around pipe surface of is location ground. monument washed

original location of this corner: Description of monument and accessories I established to perpetuate the

From Corner location as described above,

New Bearing I mark 1/4 Tree, a S21 BT. Ð 14" Spruce, bears S 45 1/20 W, a distance 0f 40.2 feet,

marked R.L.S. 1024, trunks of all trees. Attached USFS signs, . 54-3 and 54-4, new Bearing Tree.40 a11 Painted Bearing blazes Trees, , and attached and a 6" wide band around brass

o, steelfence post ρŽ East of. corner and attached USFSsign 54-4

REGISTERED PROFESSIONAL OREGÓN FEBRUARY 14, 1975 THOMAS F. UPTON mass 1024

Thomas F. Upton, Certificate No. R.L.S. 1024

I hereby certify that the within instrument was filed in this office mantra A. Hughes

Office of..

Co. Surveyur

County of MOTTOIN

Form R6-7100-57 (9/71)

RECEIVED BY

1.0. 472-K Date Lanua pu Morrow County Surveyor 1987

TAT 2 V 8/2