2-10

History of original corner establishment

surveyed The section in which this corner is surveyed under Contract Survey No. . s located was originally 417, dated 1881.

This section was later included in Deauthorized in 1938, and approved Feb. included in Dependent Resurvey d approved Feb. 21, 1941.

connection The corner identified by with either o. of this the surveys record was not noted above monumented in

> W 1/16 \$28 1981 R.L.S. 1024 DIAGRAM T5SS21

Description of corner evidence found

Corner not previously monumented.

original location of this corner: Description of monument and accessories I established to perpetuate the

marked1/2 location of this corner, as established by a inch alum. pipe, 30 inches long, 2 feet in a as shown above. survey conducted by me, the ground, with an alum.

From The monument as set,

A Bearing Tree, a 10" Spruce, marked W 1/16 S21 BT. bears2 210 W, a distance f18.5 feet, which

A Bearing Tree, a 10" Spruce, bears S 3° W, a distance of 12.6 feet, which I marked W 1/16 S 21 BT.

Painted Attached blazes USFS signs, blazes and a 54-3 and 6" wide and band 54-9, 6 and nd a brass tag marked R.L.S. florescent red around trunks. 1024, to all

a 61 steel fence post, 5' East of corner and attachtd USFS signs, 54-2 over 54-9.

OREGOTHOMAS F. U REGISTERED PROFESSIONAL AND SURVEYOR UPTON

Thomas F. Upton, Certificate No. R.L.S.1024

State of Oregon, hereby certify that the within instrument was filed in this office for record on the 12 thday of Samueline, 1982

Paule M. Krumpain by Maatra A. Hugher
(COUNTY OFFICIAL) Office of Land Sunder Here County of Morrow....

Form R6-7100-57 (9/71)

HICCITATION BA

Morrow County Surveyor фс₽О

Ref drum no C. 460 x Sed 21 Monmon