History of original corner establishment

not established in the original survey. ablished in 1979 by PLS 1106.

DIAGRAM
FOUND MONUMENT
T 4 S R 29 E
S 32
1/4 S 5
1 5 S R 29 E
1979
PLS 1106

Description of corner evidence found:

Found 3 inch br along the towns NOTE: In 1986 3 inch brass cap, 2 like township line. ground set by PLS 1106 in 1979, accepted.

north line, Section 5, set 3-1/4 inch PCI aluminum inches in the ground. Cap marked:

R 29E

NOTE: These accessories to monument established in 1986; 7 inch fir bears S. 36° W., 43.7 feet marked: X BT 13 inch larch bears S. 16° E., 101.0 feet marked: X BT Brass Cap by PLS 1106 bears N. 89° 53' 42" E., 16.34 feet.

Approximately 810 feet West to Road 170

CERTIFICATION  Ken E. Jenkins  Lectify the Information shown brein is true and correct.  Certify the Information shown brein is true and correct.  Reprint Ground Park Riber  Thomas M. S. Harrison  Certify harding the confectivity on the contract of the c

orm R6-7100-57 (9/71)

State of Oreg. O.T ...

I hereby certify

Office of .....SUXXXXXX.