## OREGON CORNER RESTORATION FORM

SECTION 3

TOWNSHIP\_ 1 SOUTH

RANGE 24 EAST

COUNTY: <u>MORROW</u>

DATE:

7/07/2022

CORNER DESIGNATION: A-15

PREVIOUS RENEWALS / SURVEYS, etc.

NO HISTORY OF MONUMENT BEING ESTABLISHED

MONUMENT and ACCESSORIES FOUND: ( CONDITION AND SOURCE )

2022: NO EVIDENCE OF CORNER FOUND.

(SEE MORROW COUNTY SURVEY 2022-1994C)

## DIAGRAM:



MONUMENT and ACCESSORIES SET ( PROCEDURES and DESCRIPTION )

SET 5/8"X30" REBAR W/ 2" ALUMINUM CAP STAMPED AS SHOWN ABOVE AT SOUTH BASE OF E-W FENCE MARKING BOUNDARY OF BASELINE. SET CARSONITE ±0.4' NORTH

(SEE MORROW COUNTY SURVEY 2022-1994C)

## REFERENCES SET:

SET 5/8"X24" REBAR WITH RED PLASTIC CAP STAMPED "RSI CONTROL" S89°55'57"E 19.31 FEET SET 5/8"X24" REBAR WITH RED PLASTIC CAP STAMPED "RSI CONTROL" S47°35'11"E 30.23 FEET SET 5/8"X24" REBAR WITH RED PLASTIC CAP STAMPED "RSI CONTROL" S27°43'25"W 22.79 FEET SET 5/8"X24" REBAR WITH RED PLASTIC CAP STAMPED "RSI CONTROL" S89°39'32"W 21.63 FEET RP-1 RP-2 RP-3 RP-4

LOCATION and COMMENTS

CORNER IS LOCATED APPROXIMATELY 350 FEET EAST OF ELLA ROAD

SURVEYORS SEAL

**REGISTERED PROFESSIONAL** 

LAND SURVEYOR

RECEIVED BY:

MORROW COUNTY SURVEYOR

DATE 8-11-2022

REC'D BY: MK

NO. ISZYAIS

FIRM / AGENCY

ROGERS SURVEYING, Inc., P.S. 1455 COLUMBIA PARK TRAIL, #201

RICHLAND, WA 99352

(509) 783-4141

OREGON MARCH 09, 2021 BRENTON A. GRIFFIN 93754PLS

RENEWS: 06/30/2023

7/7/22