

Section 17 Township 4S Range 25E
 County Morrow Date: May 4, 1998

Corner Designation: 4S25L9

1/4 corner common to sections 16 and 17,
 T4S, R25E, W.1/4.


Condition Report Only
 Not found
 Remonumented
 Unrecorded
 Surveied in
 Referenced out

Previous Renewals / Surveys, etc.


The corner was originally established by Zenas F. Moody under contract No. 184 dated August 16, 1873. His record reads "Set stone 14x10x7 for 1/4 S. Cor."

Monument and Accessories found: (condition and source)

Found a mound of stone on a bare ridge top with very little grass. Found a stone of near record dimension in the mound. There was no other stone of any size within 150 feet of the mound.



DIAGRAM



SKETCH

MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)
 Set a 2 1/4 inch brass cap on a 1 1/8" x 1' galvanized iron pipe stamped as shown in the diagram above in the mound of stone. Cemented the mound together.

REFERENCES SET:

- A 5/8" x 24" rebar with a 1 1/8 inch red plastic cap stamped ORLS 852 and WALS 13922 bears N28°50'49"E a distance of 37.60 feet.
- A 5/8" x 24" rebar with a 1 1/8 inch red plastic cap stamped ORLS 852 and WALS 13922 bears S70°47'59"E a distance of 42.15 feet.
- A 5/8" x 24" rebar with a 1 1/8 inch red plastic cap stamped ORLS 852 and WALS 13922 bears S27°32'54"W a distance of 45.10 feet.
- A 5/8" x 24" rebar with a 1 1/8 inch red plastic cap stamped ORLS 852 and WALS 13922 bears N80°16'53"W a distance of 42.78 feet.

Location and comments
 Monument and references
 located using GPS.

Compass Declination

Surveyors Seal

Firm / Agency
 Haddock Surveying
 Address
 P.O. Box 1574
 Pendleton, Or. 97801
 Party Chief
 Stephen K, Haddock

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR
David L. Haddock
 OREGON
 JULY 12, 1988
 DAVID L. HADDOCK
 852

RECEIVED BY:
 Morrow County Surveyor

Date:
 Rec'd By:
 No.