

OREGON CORNER RESTORATION REPORT

CORNER DESIGNATION: T1N, R26E, X-17

1/4 CORNER TO SECTIONS 34 & 35, TOWNSHIP 1 NORTH, RANGE 26 EAST, W.M., MORROW COUNTY, OREGON.

PREVIOUS RENEWALS / SURVEYS, ETC.:

T1N, R26E WAS ORIGINALLY SUBDIVIDED BY HAFT UNDER CONTRACT NO. 99, DATED JULY 8, 1861 IN WHICH THE NOTES READ, "DEPOSITED A PINT OF CHARCOAL SET A POST FOR QR. SEC. CORNER & RAISED A MOUND WITH TRENCH AND PITS AS PER INSTRUCTIONS".

MONUMENT AND ACCESSORIES FOUND:

NO EVIDENCE OF THE HAFT CORNER REMAINS, FALLS IN THE INTERSECTION OF SAND HOLLOW ROAD AND BASELINE LN. HELD THE THE CENTERLINE INTERSECTION OF ROADS RUNNING EAST-WEST, AND NORTH. ROAD NOTES (#181 & #224) CALL TO FOLLOW SECTION LINES AND CORNERS IN THIS LOCATION; THEREFORE, THE ROAD INTERSECTION WAS HELD AS BEST AVAILABLE EVIDENCE.

MONUMENT AND ACCESSORIES SET:

SET MAGNAIL WITH STEEL WASHER MARKED, "KENNY LS89374" IN ASPHALT. ESTABLISHED 4 REFERENCE MONUMENTS AS FURTHER DESCRIBED AND DETAILED BELOW.

REFERENCES:

- (A) SET 5/8"X30" STEEL REBAR WITH PINK PLASTIC CAP MARKED "KENNY LS 89374". CORNER BEARS S 36°25'45" E, 79.53'.
- (B) SET 5/8"X30" STEEL REBAR WITH PINK PLASTIC CAP MARKED "KENNY LS 89374". CORNER BEARS N 60°26'57" E, 45.13'.
- (C) SET 5/8"X30" STEEL REBAR WITH PINK PLASTIC CAP MARKED "KENNY LS 89374". CORNER BEARS N 61°05'58" W, 43.79'.
- (D) SET 5/8"X30" STEEL REBAR WITH PINK PLASTIC CAP MARKED "KENNY LS 89374". CORNER BEARS S 44°55'03" W, 50.31'.


LOCATION / COMMENTS:

CORNER IS LOCATED AT THE INTERSECTION OF SAND HOLLOW RD. AND BASELINE LN.

BEARING BASE:

REPORTED BEARINGS ARE BASED ON PARTITION PLAT NO. 2025-03.

DIAGRAM:



FIRM:

KENNY LAND SURVEYING
P.O. BOX 447 HEPPNER,
OR 97836

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JAN 12, 2016
MATTHEW PATRICK KENNY
89374PLS

RENEWS: 6-30-25

IN 26 X 17 2093