## OREGON CORNER RESTORATION FORM

New Accessories  None  Location & Comments  Drive through fields of Compass Decl Rita Clark Firm/Agency I  Engineering Address P.O.  Pendleton, O  Party Chief I  Notes  Witness B. K.	Monument Set (Procedures and Description) Set 2 1/2" Brass Cap in ground 18" with	524   519 1986 3 Pls 9	ACSE RESE SIS   SIS	Monument Detail	Monument(s) & Accessories Found: (Condition Found rock mound in old fnece lind with old fit called distances North-South and West rea	nce original GLO s	R 28 E R 29 E  S 13   S 18 S 24   S 19  Previous Renewals/Surveys, etc.	CORNER DESIGNATION	Section Township $1 \text{ N}$ Range $(28)$ County Date7/10/86
Surveyor's Seal  Compass Declination  Firm/Agency Krumbein  Engineering Ltd.  Address P.O. Box 1126  Pendleton, Oregon 97801  Party Chief B. Reynolds  No. 835-K  Witness B. Kopp II	and Description) ground 18" with raised rock mound		See Morrow County Surveyor Drawing No. D-828-K	Sketch	(Condition and Source) d with old fence line to East. Also d West reasonably well.		Renewed Unrecorded Surveyed In Referenced Out	Condition Report Only Not Found	1/86 N-25 E