OREGON CORNER RESTORATION RECORD

CROSS INDEX: G-21

SECTION 11 & 12 TOWNSHIP 4 NORTH RANGE 25 EAST

COUNTY MORROW DATE NOVEMBER 11, 2020

CORNER DESIGNATION: 4N25G21

1/4 CORNER COMMON TO SECTIONS 11 AND 12 T4N, R25E, W.M., MORROW COUNTY, OREGON.

TYPE OF REPORT

__ CONDITION ONLY

X NOT FOUND

_____ RENEWED

____UNRECORDED

_____ SURVEYED IN

X REFERENCED OUT


HISTORY OF ORIGINAL CORNER AND / OR PREVIOUS RENEWALS:

CORNER WAS ORIGINALLY SET BY JOHN B. DAVID UNDER CONTRACT NO. 131 DATED JUNE 8, 1869. HIS RECORD READS: SET A POST IN MOUND (VOL: OR-R0091 PG:0326.0)


DESCRIPTION OF CORNER EVIDENCE FOUND (CONDITION AND SOURCE):

FOUND A 5/8" REBAR - NO CAP - BENT NORTHWEST AS SHOWN IN C-110-K DATED AUGUST 1, 1978

DIAGRAM



SKETCH (NTS)



LOCATION / COMMENTS:

MAG. DECL. 14° 33' EAST

HORIZ DATUM: NAD83 (2011) 2010.00 PROJECTION: OREGON - NORTH (3601)

UNITS: INTERNATIONAL FEET NORTHING: 794464.61

EASTING: 8420270.51

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED:

SET A 5/8"x30" IRON ROD WITH 2" ALUMINUM CAP 2' BELOW THE SURFACE

R.P. 1 - N63°01'37"W 25.69' TO 1/2" REBAR W/R.P.C. "M&S CONTROL" R.P. 2 - S11°23'47"W 23.25' TO 1/2" REBAR W/R.P.C. "M&S CONTROL" R.P. 3 - S51°11'10"E 30.48' TO 1/2" REBAR W/R.P.C. "M&S CONTROL"

R.P. 4 - N65°22'26"E 19.61' TO 1/2" REBAR W/R.P.C. "M&S CONTROL"

MEASUREMENTS TO THE CAP AND REFERENCES WERE MADE WITH A TRIMBLE RTK GPS SYSTEM

FIRM/AGENCY NAME: MACKAY SPOSITO JOB NO: 17368

ADDRESS: 1325 SE TECH CENTER DRIVE, SUITE 140

VANCOUVER, WA 98683 (360) 695-3411

RECEIVED BY:

MORROW COUNTY SURVEYOR

DATE: 3-9-2021

RECORDED BY: MPK

NO: YNZSGZI

SURVEY NO.

2021-19186

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 13, 2004 CARLA JO MERITT 74286LS

RENEWS: DEC. 31, 2020

2/23/21