CORNER RESTORATION FORM

Township 4N Range 25E Section 20 County MORROW

State OREGON Date 10/24/2013 Number R-5

Corner Designation : SW CORNER SEC. 20

___ Condition Report Only
___ Not Found
X Renewed
___ Surveyed In
X Referenced

Previous Renewals

Monument (s) Found: (Condition and Source)

FOUND 3/4" IRON PIPE AS PER SURVEY NO. C-418-K IN LARGE TRASH PILE/HOLE 2' BELOW TRASH LEVEL, IN GOOD CONDITION BUT STANDS A GOOD CHANCE OF BEING BURIED WITH TRASH AND UP TO 10' BELOW GRADE.

Accessories Found:

FOUND 3/4 IRON PIPE 0.4' ABOVE GROUND S89°47'47"E 51.17 PLACED A 5/8" REBAR AND CAP PLS 61420 INSIDE OF PIPE. A T-POST WAS 1' SOUTH OF THE PIPE I PLACED A MORROW COUNTY WITNESS POST SIGN ON THE T-POST.

MONUMENT DETAIL

X Found ___ Set



3/4" IRON PIPE

Monument & Accessories Set (Procedure and Description)

ALL BEARINGS SHOWN HERE ARE BASED ON SURVEY NO. 2013-39D.
SET 5/8" REBAR & CAP PLS 61420 0.5' BELOW GRADE BETWEEN ROAD AND FIELD N0°28'41"E 67.96.
SET 5/8" REBAR & CAP PLS 61420 0.3' ABOVE GRADE IN A FENCE LINE S0°24'35"E 44.22.
SET 5/8" REBAR & CAP PLS 61420 0.1' ABOVE GRADE N89°47'47"W 997.11 AND T-POST SOUTH OF REBAR.
THE 3/4" PIPE AS SHOWN IN RECORD OF SURVEY NO. C-810-K HAS BEEN REMOVED.

Sketch of Monument, Accessories and General Area



Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR
OREGON
MAY 10, 2011
LANCE CLARK KING
61420
RENEWS: 6/30/2015

Agency:
CK3, LLC
945 W. ORCHARD
HERMISTON OREGON 97838
OFFICE: 541-567-2345
FAX: 541-567-2305
WEB: CK3LLC.NET

Field Book # 0-289

COUNTY SURVEYOR RECORDING INFO

Received 11-21-2013
Filed 11-25-2013
Survey No. 2013-39D
Drawing No. ___
Index No. 1686