CERTIFIED RECORD OF LAND CORNER MONUMENTATION

DIAGRAM $Z - 17 \frac{1}{2}$

History of original corner establishment:

under GLO contract No. 325, as follows: establishing the first standard parallel south, on August 13, 1879, The original position was established by Everett A. Thatcher while

"A Pine 30" in diameter". At 4.70 chains east of the standard corner to sections 34 and 35, "A Spring, SE" At 4.80 chains east of the same corner.

t	J	PLS	<u>ы</u>	<u> </u>	S	T58
9	2003		16S	. P.	S35	5S R25E
		636				SH

Original corner evidence recovered:

Found the original line tree, a large Ponderosa Pine, wind thrown and decayed. I was not able to see axe marks on this tree. This position, however, fits the record position east from the section corner to sections 34 and 35, as well as a small ravine to the east of the line tree, fed by a spring a short distance to the north of the standard parallel line.

Monument and accessories established to perpetuate the original position of this corner:

25" into the ground. A 2 1/2" brass cap attached to the top of the pipe is marked as shown in the In the center of the root hole where the line tree stood, I set a 1" x 30" flared, galvanized iron pipe diagram above. I build a mound of stones around the pipe, from which:

A 13" Ponderosa Pine, scribed "AP BT", bears N54° 30' E, 102.2 feet. A 23" Ponderosa Pine, scribed "AP BT", bears S55° W, 45.6 feet.

nailed flush to the bottom of the lower blaze The bearing trees are scribed on double blazes and have a 3/4" brass washer, marked "PLS 1636",

Magnetic declination set in compass: I hereby certify this corner point was perpetuated as hereon described on May 28, 2003 Magnetic declination set in compass: 17° E.

NAD '83 UTM Zone 11 position: 4995490N 289303E (plus or minus two meters)



Recorded at the office of County Surveyor, County of Morrow, State of Oregon, on:

Morrow County Surveyor RECEIVED BY

Date: Rec'd By: 5525 2 17. 11-4-14

Folder No.: