OREGON CORNER RESTORATION FORM

COUNTY: Morrow DATE: 05/14/04

CORNER DESIGNATION: G-9, The East Quarter Corner of Section 8, Township 5 South, Range 27 East, W.M., Morrow County, Oregon.

Sanderson under Contract No. 417, dated August 24, 1881. Record states: Set basalt stone 12 x 10 x 6 ins 8 ins in ground for 1/4 Sec. Cor. marked 1/4 on W. face, raised mound of stone PREVIOUS RENEWALS/SURVEYS ETC.: Corner originally established by Edward W.

MONUMENT AND ACCESSORIES FOUND:

Found 9 by 9 by 5" set basalt stone, at West side of 3 foot diameter mound of stones

MONUMENT MARKING DETAIL:

PLS 1106 T5S R27E S8 | S9 2004 1/4

position of found original stone I set a 2 1/2" brass disk in drilled hole and cemented it with grout MONUMENT SET: Corner falls on diced basalt rock ridge with soil depth of about 2" Marking Detail" The top of the brass disk is 2" below ground level. Disk is marked as shown in "Monument

New Accessories:

bears N 40° E, 61.5 feet. A 5/8" x 24" iron rebar with yellow plastic cap stamped "OR PLS 1106, WA PLS 17372",

A 5/8" x 24" iron rebar with yellow plastic cap stamped "OR PLS 1106, WA PLS 17372" bears S 46° E, 74.5 feet.
A 5/8" x 24" iron rebar with yellow plastic cap stamped "OR PLS 1106, WA PLS 17372"

bears N 16° W, 48.5 feet. bears S 17° W, 58.4 feet. A 5/8" x 24" iron rebar with yellow plastic cap stamped "OR PLS 1106 WA PLS 17372"

brass disk with original stone on West side, (soil is very poor, rocky on a plateau). Wired bearing object signs to all rebar accessories. Built small mound of stones around

LOCATION AND COMMENTS: Corner is located at the West side of a bare diced rock ridge There is road about 800 feet East of Corner

FIRM: William R. Wells, PLS

Pendleton, OR 97801 P.O. Box 1696

Witnesses: Jason Wells, LSIT COMPASS DECLINATION: 18° East

Marc Hammersla

/5S27G9

Morrow County Surveyor RECEIVED BY

Rec'd By: 1-08-05 D-1409-3

Folder No.:

Surveyor's Seal