## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

6

History of original corner establishment:

Unsurveyed subdivided Section.

DIAGRAM 50 28E

No record o<u>f</u> subsequent remonumentation found in County Records.

Description of corner evidence found:

evidence found.

I set the the found monument  $E \stackrel{1}{\leftarrow} and t$ the described below the computed C 1 of the midpoint between Section 15.

Description of monument and accessories I established to original location of this corner

当代 the position described above, the ground, with a brass cap , I set a  $2\frac{1}{2}$ " x 30" iron pipe 27" marked as shown:

from which I scribed BTs:

fir fir 16" in diam. bears N  $63^{\circ}$  E 30.7' 14" in diam. bears S  $40^{\circ}$  W 39.5'marked CE 1/16 S marked CE 1/16 S 15 BT.

> LAND SURVEYOR PROFESSIONAL

REGISTERED

teny OREGON
JULY 14, 1978
TER Y E. HAMBY
1638 co Hemr

nailed a brass washer marked PLS 1638 to the BT blazes.

set a steel fence post 25' North and 4' South with signs painted a red band around the BTs and face of scribe

the center used a center of E steel tape n and measured BTs. and magnetic compass with 21° ed a horizontal distance t

corner was set October 20, 1979.

Witness by Dennis L. Paasch and W. Keith Sands

54-2 ጵ 4-45 63.8 S S d 28E

Office of State of ... County Surveyor I hereby certify that the within instrument was filed in this office of DCC 1979 Morrow

(DEPUTY,

for recogn

on the

COUNTY I

RECEIVED BY

Eec'd By Date Morrow County Surveyor のこ

·} RS-7100-57 (9/71)

11

Conseponder drawing