
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishments

c originally established Contract No. 368, dated dated Sept. ₩. 7, Sanderson 1880.

field notes state:

15x13x7 stone mound for



2 grooves West face face on North face, firmly set in basalt stone 14"x12"x5" , 6 grooves on East face and 6 a mound of stone., from which: grooves on South ce and 6 grooves grooves face;

and were never entered into the official I believe to be from notes. the Original

blaze Pine, 46" in laze that was o n diam. opened bears years ago. Z 30° Blaze 72.0 e is 7 7" into tr tree. **R25E**

detached blazed chip pine stump, mkd. BT. 34" in diam. bears S 66° ₩., 36.0 ft.

See my recorded Map of Survey dated Oct. 1980.

Description of monument and accessories I established to perpetuate the

selginai location of this corner

At a point under the center of a 5/8"x30" iron pin flush with to pin. then placed und it. the the ground and attached corner stone back over the closing corner stone, the ground and attached a corner stone back over the plastic e pin as μ.

measuring Used magnetic to face of compass BT blaze. with 18° East variation and steel tape

G. 0.P.L.S

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 12, 1963
ROBERT D. BAGETT
5 9 8

PLASTIC CAP MARKED.

Survey

Marke

B-G-

...Surveyor. doy of.. November,...1980... County of MOTTOW

RECEIVED BY

Morrow County Surveyor

No. Rec'd 4

MO. # 598.