CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No.E-22

History of original corner establishment:
This corner not prev

previously established

T6S R26E 1 S1 W

Description of corner evidence found:
K tag indicates west 1/16 in general area

Description of monument and accessories I established to perpetuate the

original location of this corner:
Set a 2" I.D.
26" into the g ground galvanized and l iron pipe stamped the 30 ° cap long S shown with 2 1/2" brass cap in diagram above.

Placed steel f Survey ed a 3' diameter L fence post 5' e Y Monument and P meter collar o t 5' east of t and Property of stone around the monument and the monument with Forest Service y Boundary signs attached. set : Land QJ

bearing Bearing Nailed Scribed W1/16 S1 21.6'. Scribed W 44'W, 42.6'. Each 6'. Scribed W1/16 S12 BT on a 1" Ponderosa Pine which be 6'. Scribed W1/16 S12 BT on a 13" Douglas Fir whw, 42.6'. Each scribe is in a 24" blaze. The bealed an aluminum washer, stamped RLS 852, between T on each new bearing tree. Painted a 6" red baring trees and attached Forest Service Land Surving Tree signs. between th bears $N9^{\circ}47^{\prime}E_{\star}$, ir which bears $S4^{\circ}$ bearings are tr Survey Monument band the around letters true and W

S certify hereon the above described corner point on September was established 1987.

		٠
OREGON JULY 12, 1968 DAVID L. HADDOCK	David L. Haddock	PROFESSIONAL LAND SURVEYOR

(COUNTY OFFICIAL) by	for record on the 12 day of DECEMBER. 1996	State of DREGOA	Office of COUNTY SURVEYOR County of MORROW
(COUNTY OFFICIAL) (DEPUTY)	19.5%	at the within instrument was filed in this office	County of MORBON