


RECORD OF SURVEY

SE 1/4, SW 1/4, SECTION 29, T.5S., R.26E., W.M., MORROW COUNTY, OR.



MONUMENT TABLE

- (A) NORTHWEST CORNER OF SECTION 29. FOUND REMAINS OF BENT ALUMINUM PIPE AND CAP PER SURVEY FOLDER 812 IN SMALL MOUND OF STONE. THE CORNER HAS BEEN DISTURBED BY LOGGING ACTIVITY. HELD POINT AT WHICH THE PIPE RUNS VERTICALLY INTO THE GROUND. RECORD BEARING TREES PER FOLDER 812 REMAIN.
- B NORTH ONE-QUARTER CORNER OF SECTION 29. FOUND RECORD STONE INSIDE SMALL STONE MOUND, NO OBVIOUS MARKINGS FOUND. SET 2-1/2" BRASS CAP ON 30" FLARED GALVANIZED STEEL PIPE. SEE CORNER CERTIFICATE.
- ONORTHEAST CORNER OF SECTION 29. FOUND SMALL STONE MOUND AND 1" STEEL PIPE WITH REMAINS OF A KINZUA CORNER IDENTIFICATION TAG. I FIND A RECORD SIZE STONE BUT NO OBVIOUS MARKINGS. SET 2-1/2" BRASS CAP ON 30" FLARED GALVANIZED STEEL PIPE IN THE CENTER OF MOUND. SEE CORNER CERTIFICATE.
- EAST ONE-QUARTER CORNER OF SECTION 29. MADE EXTENSIVE SEARCH FOR RECORD STONE AND BEARING TREES, NONE FOUND. THE AREA HAS BEEN DISTURBED BY LOGGING ACTIVITY. COMPUTED LOCATION BY SINGLE PROPORTION. KINZUA CORNER TAG BEARS SOUTH 63'46'23" EAST, 9.46 FEET FROM COMPUTED LOCATION.
- E SOUTHEAST CORNER OF SECTION 29, HELD 2-1/2" IRON PIPE IN STONE MOUND PER SURVEY FOLDER 1063.
- F SOUTH ONE-QUARTER CORNER OF SECTION 29. HELD 1-1/2" I.D. IRON PIPE IN STONE MOUND PER SURVEY FOLDER 1063.
- G SOUTHWEST CORNER OF SECTION 29. AREA HAS BEEN DISTURBED BY LOGGING ACTIVITY AND FALLS ON A ROCKY KNOLL. I FOUND NO EVIDENCE OF THE ORIGINAL STONE OR MOUND IN THE VICINITY. IN MAKING A SEARCH FOR THE STONE, I FIND EVIDENCE OF OLD BARBED WIRE FENCING RUNNING EAST, WEST, AND SOUTH. I HELD THE INTERSECTION OF THE MEASURED WIRE AS BEST AVAILABLE EVIDENCE OF ORIGINAL CORNER LOCATION. SET 2-1/2" BRASS CAP ON 30" FLARED GALVANIZED STEEL PIPE WITH STONE MOUND TO CAP, SEE CORNER CERTIFICATE.
- WEST ONE—QUARTER CORNER OF SECTION 29. AREA DISTURBED BY LOGGING ACTIVITY AND A ROAD CUT RUNS THROUGH THE AREA. CORNER IS NEAR THE NORTHERLY LIMITS OF AN OPEN MEADOW. I FOUND NO EVIDENCE OF THE ORIGINAL STONE OR MOUND IN THE VICINITY. COMPUTED LOCATION ON LINE BETWEEN SOUTHWEST AND NORTHWEST CORNERS OF SECTION 32, 3 CHAINS SOUTH OF AN EXISTING SOUTHWEST RAVINE PER ORIGINAL NOTES (3). A KINZUA CORNER TAG BEARS SOUTH 51'59'29" WEST, 9.09 FEET FROM COMPUTED LOCATION.

LEGEND

- HELD EXISTING SECTION OR QUARTER SECTION CORNER AS NOTED.
- RE-ESTABLISHED SECTION OR QUARTER SECTION CORNER AS NOTED.
- SET 5/8"X30" STEEL REBAR WITH PINK PLASTIC CAP MARKED "KENNY LS 89374".
- CALCULATED POSITION ONLY. NOTHING FOUND OR SET, UNLESS NOTED OTHERWISE.
- MONUMENT IDENTIFIER, SEE MONUMENT TABLE.

)# RECORD DATA REFERENCE. SEE TABLE FOR CORRESPONDING RECORD.

SECTION LINES

RECEIVED BY

Morrow County Surveyor

Date: 10-28 - 2024

No.: 2024 - 2079C

Folder No.: 2079

Rec'd By: MPK

SECTION SUBDIVISION LINES

PROFESSIONAL
LAND SURVEYOR

OREGON
JAN 12, 2016
MATTHEW PATRICK KENNY
89374PLS

RENEWS: 6-30-25

KENNY LAND SURVEYING

P.O. BOX 447, HEPPNER, OR 97836 541-379-0242 www.kennylandsurveying.com

LOCATED IN THE SE1/4, SW1/4 OF SECTION 29, T.5S., R.26E., WILLAMETTE MERIDIAN, MORROW COUNTY, OR

CLIENT:

CYNTHIA FLATT

PROJECT: 23-53

DATE: OCTOBER 3, 2024

SHEET 2 OF 2